




PFEIFFER VACUUM
Operating Fluid Reservoir

TECHNICAL DATA

OPERATING FLUID RESERVOIR
REPLACEMENT FOR THE PFEIFFER VACUUM HIPACE 80 TURBO PUMP. TO ENSURE THE EFFICIENCY OF YOUR PUMP, THE LUBRICANT RESERVOIR SHOULD BE REPLACED AT LEAST ONCE EVERY THREE YEARS. ANY QUESTIONS, PLEASE CONTACT OUR SALES AND SERVICE DEPARTMENT.



We Can Rebuild & Service your Pfeiffer Turbo Pumps



www.AJVS.com

**Helium Leak
Detector Rentals**

**Free Repair Estimate
on all Major Brands**

Open 24-7

**Easily Generate
Service RMA**

**Large Selection of New
and Refurbished High
Vacuum Equipment**