



**PFEIFFER VACUUM**  
**Operating Fluid Reservoir**

**TECHNICAL DATA**


**OPERATING FLUID RESERVOIR**  
 REPLACEMENT FOR THE PFEIFFER VACUUM HIPACE 80 TURBO PUMP. TO ENSURE THE EFFICIENCY OF YOUR PUMP, THE LUBRICANT RESERVOIR SHOULD BE REPLACED AT LEAST ONCE EVERY THREE YEARS. ANY QUESTIONS, PLEASE CONTACT OUR SALES AND SERVICE DEPARTMENT.



**We Can Rebuild & Service your Pfeiffer Turbo Pumps**



**A & J VACUUM SERVICES, INC** **PFEIFFER VACUUM**  
**Operating Fluid Oil Reservoir**  
**SALES & SERVICE 1-973-249-0854**



**www.AJVS.com**

**Helium Leak Detector Rentals**

**Free Repair Estimate on all Major Brands**

**Open 24-7**

**Easily Generate Service RMA**

**Large Selection of New and Refurbished High Vacuum Equipment**